











DATE: 18.7.2022

<p>702019</p>  <p>L 1000</p>	<p>PCS</p> <p>3</p>	<p>702021</p>  <p>L 2000</p>	<p>PCS</p> <p>11</p>	<p>702022</p>  <p>L 910</p>	<p>PCS</p> <p>11</p>	<p>702038</p> 	<p>PCS</p> <p>4</p>	<p>702220</p> 	<p>PCS</p> <p>23</p>	<p>702227</p>  <p>L 2000</p>	<p>PCS</p> <p>6</p>
<p>702248</p> 	<p>PCS</p> <p>6</p>	<p>702286</p>  <p>65x65</p>	<p>PCS</p> <p>1</p>	<p>900240</p>  <p>Ø8x70</p>	<p>PCS</p> <p>9</p>	<p>902434</p> 	<p>PCS</p> <p>59</p>	<p>905051</p>  <p>Ø24/8.4</p>	<p>PCS</p> <p>132</p>	<p>909203</p>  <p>M8x75</p>	<p>PCS</p> <p>66</p>
<p>980107</p>  <p>Ø6x60</p>	<p>PCS</p> <p>308</p>	<p>980114</p>  <p>Ø4x20</p>	<p>PCS</p> <p>4</p>	<p>980128</p>  <p>Ø7x40</p>	<p>PCS</p> <p>118</p>	<p>980150</p>  <p>M8</p>	<p>PCS</p> <p>66</p>	<p>980152</p>  <p>Ø24/8.4</p>	<p>PCS</p> <p>9</p>	<p>P01444</p>  <p>L 3000</p>	<p>PCS</p> <p>2</p>
<p>P01445</p>  <p>L 4000</p>	<p>PCS</p> <p>3</p>										
	PCS		PCS		PCS		PCS		PCS		PCS
	PCS		PCS		PCS		PCS		PCS		PCS